REGEIVED CENTRAL PAX CENTER

DEC 12 2006

Remarks (explanation)

We found error in Fig. 6 of this application. Two different devices were numbered as 454 and two different devices were numbered 452. We submit the corrected figure and corresponding part of the specification:

Digital signal processor renumbered as 453; A/D converter renumbered as 455.

CONCLUSION

It is submitted that the present application is in form for allowance, and such action is respectfully requested.

Respectfully submitted,

	Celight, Inc.
Date:12/8/2006	By: Shoul
Date:12/8/2006	Isaac Shpantzer By:
Date:12/8/2006	Arkady Kaplan By: Aviv Salamon
Dete:12/8/2006	By: 4 W Common Yankow Achian
Date:12/8/2006	By: Jakob Khurgin
Date:12/8/2006	By: Michael Tseytlin
Date:12/8/2006	By: Dall Shing Cho
Date:12/8/2006	By: Arthur Smilett
Date:12/8/2006	By: Christopher Kerr
Date:12/8/2006	By: Del About

12200 Tech Rd. Suite 300 Silver Spring MD 20904 Tel: 301-625-7000

Pax: 301-625-7001